

Transmitted Electronically

October 21st, 2016

Tricia Edwards
On-Scene Coordinator
U.S. Environmental Protection Agency, Region 5
77 West Jackson Boulevard
Chicago, Illinois 60604

Subject: Final Removal Assessment Report

Dymet Site

Muskegon, Muskegon County, Michigan

Technical Direction Document No. S05-0001-16-05-001

SRS Contract No. EP-S5-16-01

Dear Tricia Edwards:

Sustainment and Restoration Services, LLC (SRS) Superfund Technical Assessment and Response Team (START) is submitting the enclosed Dymet Site Final Removal Assessment (RS) Report dated October 21st, 2016. If you have any questions, please contact me at (312) 220-7171.

Sincerely,

Katherine Cooper for Stacey DeLaReintrie

Katherine Cooper

START Project Manager

REMOVAL ASSESSMENT REPORT DYMET SITE - RS MUSKEGON, MUSKEGON COUNTY, MICHIGAN

Final

Prepared for:

U.S. Environmental Protection Agency, Region 5 77 West Jackson Boulevard Chicago, IL 60604

TDD No.: S05-0001-16-05-001 Date Prepared: October 21, 2016 Contract No.: EP-S5-16-01 Prepared by: SRS START Project Manager: Stacey DeLaReintrie Telephone No.: (312) 220-7171 U.S. EPA On-Scene Coordinator: Tricia Edwards Telephone No.: (734) 692-7687



79 W. Monroe Street, Suite 1119 Chicago, IL 60603

TABLE OF CONTENTS

Section Pa	<u>ige</u>
1. INTRODUCTION	. 1
2. SITE BACKGROUND	. 2
2.1 Site Description	. 2
2.2 Site History	. 2
3. REMOVAL ASSESSMENT ACTIVITIES	. 3
3.1 Site Reconnaissance	. 3
3.2 Sampling	. 5
3.3 Liquid Sampling – Drum, Container, and Pit Locations	. 6
3.4 Solid Sampling – Drum, Container, and Floor Locations	. 7
3.5 Asbestos Sampling	. 8
4. SAMPLE ANALYTICAL RESULTS	10
4.1 Liquid Sample Results	10
4.2 Solid Sample Results	11
4.3 Asbestos Sample Results	11
5. POTENTIAL SITE RELATED THREATS	13
6. SUMMARY	18

APPENDICES

- A TABLES
- B FIGURES
- C ASBESTOS SAMPLE SUMMARY REPORT
- D PHOTOGRAPHIC LOG
- E VALIDATED ANALYTICAL DATA PACKAGE



1. INTRODUCTION

Sustainment and Restoration Services LLC (SRS) performed the Removal Assessment (RS) at the Dymet Site (Site) located at 1901 Peck Street in Muskegon, Muskegon County, Michigan. SRS, the Superfund Technical Assessment and Response Team (START) contractor was tasked by the United States Environmental Protection Agency (U.S. EPA), under contract No. EP-S5-16-01 and Technical Direction Document (TDD) No. S05-0001-16-05-001, to perform this RS. START was tasked to prepare a site-specific Health and Safety Plan (HASP) and a field Sampling and Analysis Plan (SAP); procure the services of an analytical laboratory; collect drum, floor pit, solids, and asbestos containing material (ACM) samples; document on-site conditions with written logbook notes and still photographs; evaluate analytical data; and prepare this RS Report. SRS and its team subcontractor Oneida Total Integrated Enterprises (OTIE) members Katherine Cooper and Stacey DeLaReintrie conducted the field investigation and sampling on May 17th and 18th, 2016.

This RS report summarizes the Site background; discusses the assessment; provides a summary of the analytical data; and discusses potential site-related threats. The appendices for this report include tables (Appendix A), figures (Appendix B), photographic log (Appendix D) and the validated analytical data package (Appendix E).



2 SITE BACKGROUND

This section provides a description of the Site and the Site history.

2.1 Site Description

The Dymet Site is located at 1901 Peck Street, Muskegon, Michigan (Figure 1). The approximately 1.8-acre Site includes two buildings attached via an enclosed gangway. The buildings are secured by locked doors, however there are some broken and some boarded up windows. The Site is physically bounded to the south by Holbrook Avenue, to the east by Peck Street, and to the west by Sanford Street. Immediately to the north the Site is bounded by a radio station and a residential property, followed by Alpha Avenue. The Site area is a mix of residential, commercial, industrial, and recreational properties. There is a ballpark immediately across Peck Street, less than 0.1 miles to the east of the Site. Two large hospitals are located less than 0.3 miles to the north of the property and two public schools are located within a less than 0.5 miles to the north and west. According to a Michigan Department of Environmental Quality (MDEQ) report, the property has created a safety issue within the neighborhood through the evidence of graffiti and gang activity (MDEQ, 2016).

2.2 Site History

Information from the MDEQ indicates that the Site was previously utilized as a manufacturing facility of die cast tools and foundry work (MDEQ, 2016). Other operations conducted at the Site included a steam cleaning and small dry cleaning operation and a large printing operation. Dymet was classified as an operator/non-generator in 1973, then as a small quantity generator in 1981. The Site was inspected by MDEQ for potential proposal as a Brownfields project. However, because of the presence of abandoned drums, MDEQ requested U.S. EPA assistance to characterize and address drum and other material observed inside the Site buildings.

According to the Muskegon Chronicle and MLive, two fires have occurred at the Site. The first fire occurred in December 2011, followed by a second fire in August 2014 (Mlive.com, 2014). A fire marshal responding to the first fire stated that the natural gas to the building had been turned



off and the electrical wiring had been stripped (The Muskegon Chronicle, 2011). According to the articles the causes of both fires remain under investigation.



3 REMOVAL ASSESSMENT ACTIVITIES

U.S. EPA and START members performed RS activities on May 17th and May 18th, 2016. Assessment activities included site reconnaissance, field screening, and collection of potential ACM samples, floor and container solid samples, solid and liquid drum samples, liquid floor pit samples, and small container liquid samples. These RS activities are discussed below.

A site-specific SAP was developed for conducting the assessment prior to mobilizing to perform the fieldwork. The SAP described the data quality objectives (DQO), sampling strategy, sampling locations, sampling methodology, and analytical procedures for analyzing the samples.

This section summarizes site reconnaissance (subsection 3.1), sampling (subsection 3.2), liquid sampling (subsection 3.3), solids sampling (subsection 3.4), and asbestos sampling (3.5). Table 1 presents a summary of collected samples and sampling locations. Photographic documentation is provided in Appendix D.

3.1 Site Reconnaissance

U.S. EPA On-Scene Coordinator (OSC) Jeff Kimble, State of Michigan certified asbestos inspector John Pomroy, and START members mobilized to the Site on May 17th and May 18th, 2016. Site reconnaissance was performed in level "D" personal protective equipment (PPE) in accordance with the approved site-specific HASP. START calibrated the MultiRAE® Plus photoionization detector (PID) multi-gas monitor prior to conducting the Site reconnaissance. The MultiRAE® Plus PID measures carbon monoxide (CO), volatile organic compounds (VOCs), hydrogen sulfide (H2S), lower explosive limit (LEL), and oxygen(O2).

The Site is comprised of two two-story buildings. The west building had a basement. A fully enclosed gangway connected the two buildings. The Site was fenced in some areas with gaps observed on the east side of the Site. There was a large opening in the roof of the east building (see photograph 42). A large pool of water was observed near the south entrance to the west



building (see photograph 41). Some of the windows of the two buildings at the Site were boarded up to cover broken windows Vandalism through broken windows was noticed during the site reconnaissance. The gaps in the fence and the broken and boarded up windows are considered areas susceptible to potential breaches by trespassers.

Drums and containers were present inside both buildings. Drums were observed staged in groups of three to fifteen (see photographs 34-36) and contained varied amounts of material at the time of site reconnaissance. Drums labeled "Sodium Cyanide- Poison" and "Oxidizer" were observed in the main room of the west building near a staging area of numerous other drums. Two 55-gallon sodium cyanide steel drums were wrapped in plastic wrap which covered the label. The two drums were rusted and exhibited signs of deterioration. The 35-gallon oxidizer steel drum also exhibited signs of deterioration.

Numerous labeled and non-labeled small containers were found throughout the facility (see photographs 37-40). Of the labeled containers, labels indicating "Metallic Muriatic Acid", "Acrylic Enamel Reducer", "Formaldehyde", and "Paper and Frisket Cement" were observed during this reconnaissance.

Four floor pits were observed in the east building. Two floor pits appeared to contain water while the two other floor pits appeared to contain a dark oily liquid. One floor pit containing the dark oily liquid was cordoned off by a yellow caution tape tied around drums. This floor pit was below a large piece of equipment (see photograph 10). The liquid observed in this floor pit was approximately five feet below the ground surface. The second floor pit containing a dark oily liquid was partially blocked by a yellow rail (see photograph 12). This floor pit was also below a piece of equipment. The liquid observed in this floor pit was approximately six inches below the ground surface.

Spilled solids and drums containing solid material were observed in several locations throughout the facility. Several drums and containers were observed without lids and contained unknown solids (see photograph 14). Solids were also observed in piles on the floor in various areas of the east building (see photograph 16 and 18). In one area of the east building, a pile of white powder was observed spilled near a drum labeled "283LF Infiltrant" (see photograph 19).



The state certified asbestos inspector identified potential ACM in several areas throughout the facility. Those areas included piping, two boiler exteriors, bricks, air cell insulation, and a stack of window panes (see photographs 1-6). Insulation on two boilers were identified to contain potential friable ACM. One boiler was located in the east building and the other was located in the basement of the west building. Bricks containing potential ACM were located in both the west and east buildings and had a weathered appearance. Piping containing potential ACM was located throughout both buildings. The air cell insulation located near the south entrance of the west building was loose and dangling. The stack of glass window panes containing potential ACM in the caulking was observed in the basement of the east building.

3.2 Sampling

START conducted removal assessment sampling activities at the Site on May 17th and May 18th, 2016. START documented approximately 86 55-gallon drums and 118 small containers (35-gallons or less) abandoned at the Site. The amount of remaining material inside the drums and small containers varied.

During this assessment, one liquid and one solid drum sample, 3 liquid small container samples, 2 liquid floor pit samples, 4 solids samples, and 28 potential ACM samples were collected for laboratory analysis. Potential ACM samples were relinquished to MDEQ for analysis. All other sample containers were labeled and preserved on ice and shipped to the laboratory for analysis. Samples collected from the Site are summarized in Table 1. Figure 2 shows the sample locations.



Based on these observations, EPA implemented a sampling strategy to verify and document the suspected wastes with off-site laboratory analysis. EPA selected the following containers and/or waste for sampling:

Table 1 Removal Assessment Sample Summary Dymet Site Muskegon, Muskegon County, Michigan							
Sample ID	Matrix	Sample Description (Markings/Labels)	Sample Location				
DYM-DR-01	Solid	55-gallon drum labeled "Sodium Cyanide"	West building				
DYM-DR-02	Liquid	35-gallon drum labeled "Oxidizer" and "Corrosive"	West building				
DYM-SC-01	Liquid	1-gallon container labeled "Muriatic Acid"	West building				
DYM-SC-02	Liquid	Duplicate sample of DYM-SC-01	West building				
DYM-SC-03	Liquid	1-gallon container labeled "Acrylic Enamel Reducer"	West building				
DYM-FLP-01	Liquid	Floor pit designated 01	East building				
DYM-FLP-02	Liquid	Floor pit designated 02	East building				
DYM-SOL-03	Solid	55-gallon open drum containing gray fine material	East building				
DYM-SOL-05	Solid	Coarse material pile on the ground	East building				
DYM-SOL-06	Solid	55-gallon open drum containing gray fine material	East building				
DYM-SOL-07	Solid	Fine white material pile on the ground near 55-gallon drum labeled "283LF Infiltrant"					

3.3 Liquid Sampling – Drum, Container, and Pit Locations

START collected six liquid samples, including one drum sample, three small container samples, and two floor pit samples. All drum samples were collected while wearing Level B personal protective equipment (PPE). All other liquid samples were collected while wearing Level D PPE.

Liquid drum sample DYM-DR-02 was collected from a drum labeled "Oxidizer" and "Corrosive" using a dedicated glass drum thief (see photographs 24-26). The liquid was clear



in color. The drum from which the sample was collected showed signs of deterioration. The liquid drum sample was analyzed for corrosivity determination by pH in accordance with EPA Method E150.1.

START collected three small container liquid samples, including one duplicate sample. The small container liquid samples were collected by decanting the container contents directly into lab-supplied glass jars. Sample DYM-SC-01 and its duplicate sample DYM-SC-02 were collected from a small container labeled "Muriatic Acid". Muriatic acid is otherwise known as hydrochloric acid. Three one-gallon plastic containers labeled "Muriatic Acid" were stored together. All three of the containers were full. Sample DYM-SC-03 was collected from a small steel container labeled "Acrylic Enamel Reducer" (see photograph 20). Only one container labeled "Acrylic Enamel Reducer" was observed. All samples collected from the small containers were clear liquids. All of the sampled small containers were located in the basement of the east building.

Two of the liquid small container samples (DYM-SC-01 and DYM-SC-02) were analyzed for corrosivity determination by pH in accordance with EPA Method E150.1. One liquid small container (DYM-SC-03) was analyzed for ignitability determination by flashpoint in accordance with EPA SW-846 Method 1010.

START collected two liquid floor pit samples (DYM-FLP-01 and DYM-FLP-02). Sample DYM-FLP-01 was collected using a dedicated sample cup. Sample DYM-FLP-02 was collected using a dedicated bailer. Both of the samples were dark oily liquids. Sample DYM-FLP-02 had an oily liquid top layer and a water bottom layer.

The two liquid floor pit samples were analyzed for total and Toxicity Characteristic Leaching Procedure (TCLP) metals plus zinc, copper, and nickel, and polychlorinated biphenyls (PCBs). Analyses were performed in accordance with EPA SW-846 Method 1311 and 6020 for TCLP metals plus zinc, copper, and nickel, EPA SW-846 Method 1311 and 7470A for TCLP mercury, EPA SW-846 Method 6020 for Total metals plus zinc, copper, and nickel, EPA SW-846 Method 7471A for mercury, and EPA SW-846 Method 8082 for PCBs



3.4 Solids Sampling – Drum, Container, and Floor Locations

START collected five solid samples, including one solid drum sample, two floor solids samples, and two container solids samples. All solid samples were collected while donning Level D PPE.

START collected solid drum sample DYM-DR-01 using a dedicated trowel from one of the two drums labeled "Cyanobrik Sodium Cyanide" (see photographs 24-26). The solid sample was a coarse sandy material and was dark brown in color. The two drums labeled "Cyanobrik Sodium Cyanide" were stored together wrapped with plastic wrap. The sampled drum was full while the quantity of the second drum is unknown as it was not opened. The solid drum sample was analyzed for amendable cyanide, total metals plus zinc, copper, and nickel, and reactivity. Analyses were performed in accordance with EPA SW-846 Method 9012A for amenable cyanide, EPA SW-846 Method 7471A for mercury, and EPA SW-846 Method 7.3.3.2 and 7.3.4.2 for reactivity determination.

START collected 2 floor solids and 2 container solids samples, using dedicated equipment and labeled them as DYM-SOL-03, DYM-SOL-05, DYM-SOL-06, and DYM-SOL-07 (see photographs 13-19). Samples DYM-SOL-03 and DYM-SOL-06 were collected from open drums containing gray fine material. Sample DYM-SOL-05 was a floor solids sample collected from a coarse material pile of small metal pieces and dirt on the ground. Sample DYM-SOL-07 was a floor solids collected from a pile of fine white powder near a drum labeled "283LF Infiltrant". The fine white powder quickly became dust when disturbed. The solids samples were transferred directly into lab-supplied glass jars using the dedicated trowel or cup.

The four solids samples were analyzed for TCLP metals plus zinc, copper, and nickel in accordance with EPA SW-846 Method 1311 and 6020, EPA SW-846 Method 1311 and 7470A for TCLP mercury, for Total metals plus zinc, copper, and nickel in accordance with EPA SW-846 Method 6020 EPA, and SW-846 Method 7471A for mercury.



3.5 Asbestos Sampling

A total of 28 potential ACM samples were collected from the piping, bricks, boiler, and glass window panes by a State of Michigan certified asbestos inspector. Nine of the samples (HA-001-HA-009) were noted as friable by the asbestos inspector. Samples HA-001, HA-002, HA-003 were collected from air cell insulation located near the south entrance of the west building. The asbestos inspector estimated the total quantity of air cell insulation material in this area to be 90 linear feet (LF). Samples HA-004, HA-005, HA-006 were collected from magnesia (MAG) piping in the basement boiler. The total quantity of MAG piping in the basement boiler was estimated to be 900 LF. Samples HA-007, HA-008, and HA-009 were collected from the MAG facing of the boiler located in the east building. The total quantity of MAG boiler facing material was estimated to be 1,440 square feet (ft2). Of the nine samples collected, only samples HA-001, HA-002, HA-003 were collected from loose, dangling, and on the floor potential ACM. The other six samples collected from the east building boiler and the basement boiler (HA-004 through HA-009) were collected from intact potential ACM. The asbestos inspector's sample description notes are included in Appendix C Asbestos Sample Summary Report. Potential ACM samples were relinquished and submitted to MDEQ for analysis of asbestos determination in accordance with EPA 600/R-93/116 Method.



4 SAMPLE ANALYTICAL RESULTS

START reviewed the sample analytical data and supporting quality assurance/quality control (QA/QC) data provided by STAT Analysis Corporation and performed data validation of the results. The validated analytical data package is included in Appendix E. Based on START's data validation, the data are acceptable for use as qualified.

The following section summarizes laboratory analytical results for samples collected during the Removal Assessment. For purposes of evaluating hazardous characteristics, sample analytical results were compared to the Code of Federal Regulations (CFR) sections 40 CFR § 261.21, § 261.22, § 261.23, and § 261.24 which verify the characteristics of a hazardous waste for ignitability, corrosivity, reactivity, and toxicity, respectively. Sample analytical results for amenable cyanide were compared to the Treatment Standards for Hazardous Wastes listed in 40 CFR 268.40. Table 3, Table 4, and Table 5 summarize all detected analytical sample results.

4.1 Liquid Sample Results

The results for liquid samples collected from the drums and containers indicated a pH of less than 2 standard units (SU) in all three samples analyzed for pH (DYM-DR-02, DYM-SC-01, and DYM-SC-02). The results of <2.0 SU, exhibits the characteristic of corrosivity and has the EPA Hazardous Waste Number of D002 as defined under 40 CFR § 261.22.

Analytical results from sample DYM-SC-03 documented liquid having a flash point temperature less than 32 degrees Fahrenheit (°F). A liquid exhibits the characteristic of ignitability and has the EPA Hazardous Waste Number of D001 as defined under 40 CFR § 261.21, if it has a flash point temperature of less than 140 °F. Analytical results for flashpoint and pH are shown in Table 4.

4.2 Solid Sample Results

Analytical results from sample DYM-DR-01 documented solids having a reactive cyanide detection of 1,500 milligrams per kilogram (mg/kg). The laboratory report also indicated that the solids from sample DYM-DR-01 effervesced and went through a color change upon addition of



strong acid. A solid waste exhibits the characteristic of reactivity as stated in 40 CFR § 261.23 if it is a cyanide bearing waste which, when exposed to pH conditions between 2 and 12.5, can generate toxic gases, vapors or fumes in a quantity to sufficient to present a danger to human health of the environment. The reactive cyanide result of 1,500 mg/kg indicates a cyanide bearing waste which exhibits the characteristic of reactivity and has the EPA Hazardous Waste Number D003. Sample DYM-DR-01 analytical results also indicated a cyanide amendable to chlorination concentration of 27,000 mg/kg, which was significantly above the amenable cyanide value for nonwastewaters of 30 mg/kg listed in 40 CFR 268.40 Treatment Standards for Hazardous Waste table. Sample analytical results for reactive and amenable cyanide are shown in Table 4.

Analytical results for TCLP metals indicated one cadmium detection above the TCLP limit of 1 milligram per liter (mg/L) as stated in 40 CFR § 261.24. The sample result for sample DYM-DR-01 indicated a cadmium concentration of 240 mg/L. The result of 240 mg/L exhibits the characteristic of toxicity and has the EPA Hazardous Waste Number of D006 as defined under 40 CFR § 261.24. TCLP analytical results are shown in Table 3.

Analytical results for the solid samples collected from the floor spill areas did not exceed MDEQ Direct Contact Criteria for non-residential soil listed in Table 3 of Part 201. Analytical results for PCBs did not indicate any PCB detections in the liquid samples collected from the floor pits.

4.3 Asbestos Sample Results

The results for samples collected from the piping, boiler, insulation, floor tile, window glass, and air cell insulation confirmed ACM in 14 of the 28 samples collected. ACM is defined by 15 USC 2642 as any material containing more than 1% asbestos by weight. All of the samples noted as friable by the asbestos inspector (HA-001 through HA-009) were confirmed to be ACM. Friable asbestos material is defined by 40 CFR §61.141 as any material containing more than 1% asbestos by weight that when dry can be crumbled or reduced to powder by hand pressure. Sample results from air cell insulation samples HA-001, HA-002, HA-003 indicated 30% chrysotile. The asbestos inspector estimated the total quantity of air cell insulation to be 90 LF. Sample results from basement boiler MAG piping samples HA-004, HA-005, and HA-006,



indicated 20% chrysotile and 2% crocidolite. The estimated total quantity of the basement boiler MAG piping is 900 LF. Samples results from the east building boiler MAG facing samples HA-007 and HA-008 indicated 20% chrysotile. Sample HA-007 also indicated 2% crocidolite. Sample HA-009 indicated the highest chrysotile detection in samples noted as friable at 25%. The total quantity of the east building boiler MAG facing material was estimated by the asbestos inspector to be 1,440 ft². The total estimated quantity of friable ACM was 990 LF and 1,440 ft² Friable asbestos is listed as a hazardous substance according to 40 CFR Part 302, Table 302.4. Asbestos sample analytical results are shown in Table 5.



5 POTENTIAL SITE RELATED THREATS

Threats posed by on-site contamination and Site conditions were evaluated in accordance with The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) criteria for initiating a removal action listed under Title 40 of the CFR, Section 300.415(b) (2). Paragraph (b) (2) of 40 CFR Section 300.415 lists factors to be considered when determining the appropriateness of a potential removal action at a site. Potential site-related threats to human health and the environment were evaluated based on the criteria listed in 40 CFR, Sections 261.21 through 261.24 and 40 CFR Part 302, Table 302.4. Factors that may be applicable to the Site are discussed below.

Actual or potential exposure of nearby human populations, animals, or the food chain to hazardous substances or pollutants or contaminants $(40\ CFR\ 300.415(b)(2)(i))$

Analytical results of the samples collected during this removal assessment indicated corrosive, ignitable, toxic, and reactive characteristic waste at the Site. Some of the windows of the two buildings at the Site were boarded up to cover broken windows. The potential for trespassers is likely at the site as there were people walking around in the area and also based on the state's reporting of graffiti and gang activity. Vandalism was evident through the numerous broken windows identified during the site reconnaissance. Also, two previous fires occurred at the abandoned property, and their cause is not yet determined. The gaps in the fence, the broken and boarded up windows (vandalism), and undetermined fires point to actual or potential exposure to nearby human populations. Analytical results from samples DYM-DR-02, DYM-SC-01, and DYM-SC-02 indicate pH levels less than 2 SU. This result, per 40 CFR § 261.22, exhibits the characteristic of corrosivity (D002).

Analytical results from sample DYM-SC-03 indicated a flash point temperature of less than 140 °F. This result, per 40 CFR § 261.21, exhibits the characteristic of ignitability (D001).

Sample DYM-DR-01 analytical results indicated a cadmium concentration above the TCLP limit of 1 mg/L at 240 mg/L. This result, per 40 CFR § 261.24, exhibits the hazardous waste characteristic of toxicity (D006).



Cadmium is a naturally occurring element found in the earth's crust. It has many uses including batteries, pigments, metal coatings and plastics. Humans exposed to high levels of cadmium through inhalation or ingestion may experience severe damage to the lungs and stomach irritation leading to vomiting and diarrhea. The Department of Health and Human Services (DHHS) has determined that cadmium is a known human carcinogen (ATSDR, 2012).

Analytical results from sample DYM-DR-01 documented solids having a reactive cyanide detection of 1,500 mg/kg. According to 40 CFR 261.23 a cyanide or sulfide bearing waste which, when exposed to pH conditions between 2 and 12.5, can generate toxic gases, vapors or fumes in a quantity sufficient to present a danger to human health or the environment. The laboratory report indicated that the solids from sample DYM-DR-01 effervesced and went through a color change upon addition of strong acid. This effervescence reaction of the cyanide sample with acid meets the definition of a hazardous characteristic per 40 CFR § 261.23 - specifically the hazardous waste characteristic of reactivity (D003). The National Institute for Occupational Safety and Health (NIOSH) states that sodium cyanide (as CN) is an Immediate Danger to Life and Health (IDLH) at concentrations of 25 milligrams per meter cube (mg/m³). Sample DYM-DR-01 results indicated a cyanide concentration of 27,000 mg/kg. This cyanide concentration under right conditions could potentially release poisonous gases exceeding the IDLH value and be fatal to human populations. This cyanide concentration is also significantly above the amenable cyanide value for nonwastewaters of 30 mg/kg listed in 40 CFR 268.40 Treatment Standards for Hazardous Waste table.

The drum labeled "Sodium Cyanide" from which sample DYM-DR-01 was collected, was located in the same room as the "Oxidizer" drum from which sample DYM-DR-02 was collected. Sample results from sample DYM-DR-02 indicated a pH less than 2 SU. Both the "Sodium Cyanide" and the "Oxidizer" labeled drums were beginning to show signs of deterioration, such as rust.

Cyanide is usually found joined with other chemicals to form compounds. Cyanide is used in electroplating, metallurgy, manufacture of plastics, and some mining processes. Humans exposed to high levels of cyanide may experience heart and brain damage, coma, and death (ATSDR,



2006).

The analytical results for the potential ACM samples collected from the piping, boiler, insulation, floor tile, window glass, and air cells confirmed ACM in 14 of the 28 samples collected. Out of the 14 confirmed ACM samples, nine samples were noted as friable by the asbestos inspector. Of the nine samples noted as friable, samples HA-001, HA-002, and HA-003 were collected from loose and dangling air cell insulation located near the south entrance of the west building. Sample results from those three samples indicated 30% chrysotile. The other confirmed friable ACM samples (HA-004 through HA-009) were collected from the boiler insulation and facing. Friable asbestos is a listed hazardous substance according to 40 CFR Part 302, Table 302.4.

Asbestos is the name of a group of six fibrous minerals (amosite, chrysotile, crocidolite, tremolite, actinolite, and anthrophyllite) that naturally occur in the environment. Asbestos has historically been used in building materials, friction products, heat-resistant fabrics, packaging, gaskets, and coatings. Human exposure to asbestos through inhalation may result in scar-like tissue in the lungs and the pleural membrane (lining) surrounding the lung. The DHHS, the World Health Organization (WHO), and the EPA have determined that asbestos is a human carcinogen (ATSDR, 2001).

The presence of confirmed hazardous material, the potential breach areas, and the history of fires at the Site pose a threat to current and nearby residents and to trespassers through direct exposure. Human contact with these materials can result in exposure to corrosive, ignitable, toxic, and reactive hazardous materials.

Hazardous substances or pollutants or contaminants in drums, barrels, tanks, or other bulk storage containers that may pose a threat of release (40 CFR 300.415(b)(2)(iii))

During the Site investigation, U.S. EPA and START observed and documented the presence of 86 55-gallon drum and 118 small containers (35-gallons or less). Containers with labels such as "sodium cyanide", "oxidizer", and "corrosive" were present at the Site. Numerous containers were in poor and dilapidated condition. Samples exhibiting the hazardous waste characteristics



of ignitability, reactivity, corrosivity, and toxicity (DYM-DR-01, DYM-DR-02, and DYM-SC-03) were collected from rusted drums or containers (see photograph 21-26). These drums could continue to rust and potentially release hazardous characteristic materials and/or related gases.

Analytical results of the samples confirmed the presence of ignitable, corrosive, and reactive hazardous waste at the Site. Drum contents were observed spilled onto the floor inside the buildings at the Site. Some containers were open without a lid and deteriorating. Continued deterioration of the containers on-site may lead to the release of hazardous substances and migration of the hazardous material to off-site locations. In addition to this, the deteriorating drum conditions can potentially lead to mixing of oxidizer and sodium cyanide chemicals and release of potential poisonous gases that could migrate to off-site locations and pose an IDLH threat to nearby residents.

Weather conditions that may cause hazardous substances or pollutants or contaminants to migrate or be released (40 CFR 300.415(b)(2)(v))

Existing weather conditions coupled with the areas accessible to precipitation at the Site may cause the hazardous substances described above to migrate or be released. The broken and boarded up windows, openings in the roof, and large puddles of water at the Site indicate precipitation at the Site. Muskegon, Michigan receives an average annual rainfall of 33.51 inches per year and an average annual snowfall of 93 inches (USclimatedata.com, 2016). The water from the roof leaks coupled with weather conditions could enable further rusting of the drums causing hazardous substances to be released at the Site. There are cyanide bearing drums at the Site with reactive cyanide material in them that when released due to rusting conditions could come in contact with similarly released acids from drums and potentially release cyanide gases. Cyanide gas is a poisonous gas and is lethal to human beings at or above the IDLH concentration of 25 mg/m³. The result of 1,500 mg/kg reactive cyanide can be released to the air.

Friable ACM is present in the boiler insulation and in loose, dangling insulation, and the floor material. Sample results from those three samples indicated 30% chrysotile. Fallen, loose and dangling ACM are indicative of deteriorating insulation and could become air borne and migrate to off-site areas posing potential exposure threats to human populations from friable ACM.



Threat of fire or explosion (40 CFR 300.415(b)(2)(vi))

Analytical results from sample DYM-SC-03 indicated a flash point temperature of less than 140 °F. This result, per 40 CFR § 261.21, exhibits the characteristic of ignitability (D001). The drum labeled "Regular Mineral Spirits" located in the southeast corner of the east building also poses a threat of fire or explosion. While it was not sampled, the material safety and data sheet (MSDS) for Regular Mineral Spirits states the flashpoint as 108°F, which exhibits the characteristic of ignitability (CITGO, 2009). There have been two fires reported to have occurred at the Site in the past 5 years according to local media outlets (MLive.com, 2014; The Muskegon Chronicle, 2011). Any fire at the Site has the potential to release hazardous material to the atmosphere and expose nearby residents to the toxic fumes related to the fire.



U.S. EPA and START conducted a removal assessment at the Dymet Site located in Muskegon, Michigan on May 17th and May 18th, 2016. Field screening with a PID for VOCs was performed on drum and other container contents prior to sampling. During sampling, one liquid and one solid drum sample, two liquid floor pit samples, three liquid small container samples, four solids samples, and 28 asbestos samples collected. Liquid and solid samples were submitted to an analytical laboratory for pH, reactivity, and flashpoint determination, TCLP metals plus zinc, copper, and nickel, Total metals plus zinc, copper, and nickel, amenable cyanide, PCBs, and asbestos analyses.

The pH results for samples collected from the drums and containers indicated a pH of less than 2 standard units (SU) in all three of the samples analyzed for pH (DYM-DR-02, DYM-SC-01, and DYM-SC-02). The result according to 40 CFR § 261.22 exhibits the characteristic of a hazardous waste for corrosivity. Analytical results from sample DYM-SC-03 documented liquid having flash point less than 140 °F, which, according to 40 CFR § 261.21, exhibits the characteristic of a hazardous waste for ignitability. Information provided by the MSDS for Regular Mineral Spirits also identifies the drum labeled as "Regular Mineral Spirits" located in the east building as containing a liquid with a flash point of less than 140 °F, exhibiting the characteristic for ignitability.

The TCLP analytical results for the sample DYM-DR-01 indicated a cadmium concentration above the TCLP limit of 1 mg/L in this sample at 240 mg/L. This result, per 40 CFR § 261.24, exhibits the hazardous waste characteristic of toxicity.

Analytical results from sample DYM-DR-01 documented solids having a reactive cyanide detection of 1,500 mg/kg. According to 40 CFR 261.23 a cyanide or sulfide bearing waste which, when exposed to pH conditions between 2 and 12.5, can generate toxic gases, vapors or fumes in a quantity sufficient to present a danger to human health or the environment. NIOSH states Sodium Cyanide (as CN) is an IDLH at 25 mg/m3. Sample DYM-DR-01 results also indicated a cyanide concentration of 27,000 mg/kg, significantly above the amenable cyanide value for nonwastewaters of 30 mg/kg listed in 40 CFR 268.40 Treatment Standards for



Hazardous Waste table.


Abandoned drums, containers, floor solids, floor pits, and ACM are present on the abandoned Dymet property. Based on the proximity of residential and recreational properties coupled with the potential breach areas and the history of fires, the ACM, corrosive, ignitable, toxic, and reactive wastes pose a potential direct contact threat to the public. The ignitable waste also poses an additional potential threat of fire and release to the environment.



REFERENCES

- ATSDR. "Toxicological profile for Asbestos." Agency for Toxic Substances and Disease Registry, U.S. Department of Health and Human Services, Public Health Service, Sep. 2001. www.atsdr.cdc.gov/toxprofiles/TP.asp?id=30&tid=4. Accessed 12 Jun. 2016.
- ATSDR. "Toxicological profile for Cadmium." Agency for Toxic Substances and Disease Registry, U.S. Department of Health and Human Services, Public Health Service, Sep. 2012. www.atsdr.cdc.gov/toxprofiles/TP.asp?id=48&tid=15. Accessed 12 Jun. 2016.
- ATSDR. "Toxicological profile for Cyanide." Agency for Toxic Substances and Disease Registry, U.S. Department of Health and Human Services, Public Health Service, Jul. 2006. www.atsdr.cdc.gov/toxprofiles/TP.asp?id=72&tid=19. Accessed 12 Jun. 2016.
- 4. US Climate Data. "Climate Muskegon Michigan". US Climate Data, 2016. www.usclimatedata.com/climate/muskegon/michigan/united-states/usmi0584. Accessed 12 Jun. 2016.
- Medendorp, Lisa. "Muskegon Firefighters Respond to Early-Morning Blaze at Vacant Factory". MLive. The Muskegon Chronicle, 26 Dec. 2011. www.mlive.com/news/muskegon/index.ssf/2011/12/muskegon_firefighters_respond_1. html. Accessed 12 Jun. 2016.
- Michigan Department of Environmental Quality. "Brownfield Redevelopment Assessment Work Plan for Dymet Facility", May 2016
- Peters, Heather. "Old Factory Building in Muskegon Damaged by Fire for Second Time in Three Years." Mlive, 25 Aug. 2014.
 www.mlive.com/news/muskegon/index.ssf/2014/08/old_factory_building_muskegon.ht
 ml.
 Accessed 12 Jun. 2016.
- Regular Mineral Spirits; MSDS No. 19015; CITGO Petroleum Corporation: Rolling Meadows, IL, 26 Aug. 2009. www.docs.citgo.com/msds_pi/19015.pdf. Accessed 12 Jun. 2016.





APPENDIX A TABLES



Table 2 Removal Assessment Sample Analysis Summary Dymet Site

Muskegon, Muskegon County, Michigan

Sample ID	Collection Date	Sample Location	Matrix	Laboratory Analysis ^a	
		Drum labeled Sodium		Amenable Cyanide, Total Metals, and	
DYM-DR-01	5/17/2016	Cyanide	Solid	Reactivity	
DYM-DR-02	5/17/2016	Drum labeled Oxidizer	Liquid	Corrosivity	
DYM-FLP-01	5/18/2016	Floor Pit	Liquid	Total Metals, PCBs, and TCLP metals	
DYM-FLP-02	5/18/2016	Floor Pit	Liquid	Total Metals, PCBs, and TCLP metals	
DYM-SOL-O3	5/18/2016	Container Solids	Solid	Total Metals and TCLP metals	
DYM-SOL-05	5/18/2016	Floor Solids Solid		Total Metals and TCLP metals	
DYM-SOL-06	5/18/2016	Container Solids	Solid	Total Metals and TCLP metals	
DYM-SOL-07	5/18/2016	Floor Solids Solid		Total Metals and TCLP metals	
DYM-SC-01	5/18/2016	Small Container labeled Muriatic Acid	Liquid	Corrosivity	
DYM-SC-02 ^b	5/18/2016	Small Container labeled Muriatic Acid	Liquid	Corrosivity	
DYM-SC-03	5/18/2016	labeled Acrylic Enamel Reducer	Liquid Flammability		

Notes:

All samples submitted for Total and TCLP Metals analyses also included zinc, copper,

b Sample DYM-SC-02 is the duplicate sample of sample DYM-SC-01

DYM Dymet Site
DR Drum Sample
FLP Floor Pit Sample
SOL Solids Sample

SC Small Container Sample

TCLP Toxicity Characteristic Leaching Procedure

PCBs Polychlorinated Biphenyls

Samples were submitted to STAT Analysis laboratory for analysis under TDD No. S05-0001-16-05-001.

Table 3 **Sample TCLP Analytical Results Dymet Site**

Muskegon, Muskegon County, Michigan

		Sample ID	DYM-DR-01	DYM-FLP-01	DYM-FLP-02	DYM-SOL-03	DYM-SOL-05	DYM-SOL-06	DYM-SOL-07	
	Col	lection Date	5/17/2016	5/18/2016	5/18/2016	5/18/2016	5/18/2016	5/18/2016	5/18/2016	
Analysis	Analyte	TCLP	_							
Method	(mg/L)	(mg/L)			K	esult Concentration	(mg/L)			
SW6020	Arsenic	5	< 5.0	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	
SW6020	Barium	100	< 25	< 0.050	0.086	< 0.050	0.35	< 0.050	< 0.050	
SW6020	Cadmium	1	240	0.069	< 0.010	< 0.010	0.3	0.039	< 0.010	
SW6020	Chromium	5	< 5.0	< 0.010	< 0.010	< 0.010	0.013	0.033	< 0.010	
SW6020	Copper	*	< 50	3	7	< 0.10	270	< 0.10	0.35	
SW6020	Lead	5	3.1	0.043	0.041	< 0.0050	0.39	< 0.0050	< 0.0050	
SW6020	Nickel	*	< 5.0	0.08	0.15	0.69	3.9	0.99	0.59	
SW6020	Selenium	1	< 5.0	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	
SW6020	Silver	5	< 5.0	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	< 0.010	
SW6020	Zinc	*	< 25	4.6	1	0.69	100	3.3	< 0.050	
SW7470A	Mercury	0.2	< 0.00020	< 0.00020	< 0.00020	< 0.00020	< 0.00020	< 0.00020	0.00020 U	

Notes:

DYM Dymet Site DR Drum Sample FLP Floor Pit Sample SOL Solids Sample milligram per liter mg/L Less than <

TCLP value not provided

bold/highlighted Sample result detected exceeding the TCLP limit.

Samples were compared to the Toxicity Characteristic Leaching Procedure (TCLP) limits as stated in 40 CFR § 261.24. Samples were submitted to STAT Analysis laboratory for analysis under TDD No. S05-0001-16-05-001.

Table 4 Flashpoint, pH, and Cyanide Analytical Results Dymet Site

Muskegon, Muskegon County, Michigan

Trubhegon County, Themgun									
	40 0777 0 0 44 04	Sample Identification							
Parameter	40 CFR § 261.21, 261.22, 261.24, and 268.40	DYM-DR-01	DYM-DR-02	DYM-SC-01	DYM-SC-02 ^a	DYM-SC-03			
	Collection Date		5/17/2016	5/18/2016	5/18/2016	5/18/2016			
Flashpoint (°F)	<140 °F					<32			
pH (SU)	≤2 or ≥12.5		<2.0	<2.0	<2.0				
Reactive Cyanide (mg/kg)	*	1500							
Amenable Cyanide (mg/kg)	30	27,000							

Notes:

< Less than

≤ Less than or equal to≥ Greater than or equal to

DYM Dymet Site
DR Drum Sample

SC Small Container Sample

°F Fahrenheit SU Standard Unit

mg/kg milligram per kilogram

Sample DYM-SC-02 is the duplicate sample of DYM-SC-01.

* Numeric value not provided in 40 CFR 261.23 (a)(5)

bold/highlighted= Sample result detected as meeting requirements of characteristic hazardous waste or exceeding

Treatment Standards for Hazardous Waste.

Samples were compared to the characteristics of a hazardous waste for ignitability, corrosivity, and reactivity criteria as stated in 40 CFR § 261.21, 261.22, and 261.23.

Sample DYM-DR-01 was compared to the Treatment Standards for Hazardous Waste listed in 40 CFR 268.40 Samples were submitted to STAT Analysis laboratory for analysis under TDD No. S05-0001-16-05-001.

Table 5 Asbestos Sample Results Dymet Site

Muskegon, Muskegon County, Michigan

Sample ID	Sample Description		Quantity	Friable Material (Y/N)	Chrysotile (%)	Crocidolite (%)
HA-001	Air Cell		30 LF	Y	30	<1
HA-002	Air Cell		30 LF	Y	30	<1
HA-003	Air Cell		30 LF	Y	30	<1
HA-004	MAG Piping		300 LF	Y	20	2
HA-005	MAG Piping		300 LF	Y	20	2
HA-006	MAG Piping		300 LF	Y	20	2
		Canvas			<1 <1	<1 <1
HA-007	MAG Facing	Wrap	-480 ft^2	Y	20	2
		Gray White			20	<1
	MAG Facing	Wrap		Y	<1	<1
HA-008		Gray	480 ft ²		20	<1
		White			<1	<1
HA-009	MAG Facing	Canvas	480 ft ²	Y	<1	<1
HA-009		Mud			25	<1
HA-010	Floor Tile + Mastic	Tile	2,250 ft ²	N	3	<1
		Mastic				<1
	Floor Tile +	Tile			3	<1
HA-011	Mastic	Mastic	2,250 ft ²	N	<1	<1
	Wastie	Glue			<1	<1
HA-012	Floor Tile +	Tile	2250 ft ²	N	3	<1
	Mastic	Mastic	223010		<1	<1
HA-013	Insulation		N/A	N	<1	<1
HA-014	Wall Coating		12,000 ft ²	N	<1	<1
HA-015	Wall Coating	White Tan	12,000 ft ²	N	<1 <1	<1 <1
		1 a11			<u>^1</u>	<u>^1</u>

Notes:

bold/highlighted= Sample result detected above reporting limit

N/A Not applicable LF Linear feet ft^2 Square feet

Friable asbestos material is defined by 40 CFR §61.141 as any material containing more than 1% asbestos by weight that when dry can be crumbled or reduced to powder by hand pressure.

Samples were analyzed in accordance with test methods EPA 600/R-93/116 Method.

Samples were collected on May 17, 2016 and submitted to Michigan OSHA/Occupational Health Laboratory for analysis under TDD No. S05-0001-16-05-001.

Table 5 continued Asbestos Sample Results Dymet Site

Muskegon, Muskegon County, Michigan

Sample ID	Sample Desc	ription	Quantity	Friable Material (Y/N)	Chrysotile (%)	Crocidolite (%)
HA-016	Wall Coating	White Tan	12,000 ft ²	N	<1 <1	<1 <1
HA-017	Lathe	White Tan	1,000 ft ²	N	<1 <1	<1 <1 <1
HA-018	Lathe	White Tan	1,000 ft ²	N	<1 <1	<1 <1
HA-019	Lathe	White Tan	1,000 ft ²	N	<1 <1	<1 <1
HA-020	Furnace Brick		3,280 ft ²	N/A	<1	<1
HA-021	External Insulation		N/A	N/A	<1	<1
HA-022	External Insulation		N/A	N/A	<1	<1
HA-023	Pipe Run	White Tan	20 LF	N/A	20 <1	<1 <1
HA-024	Pipe Run Elbow	Canvas Gray Brown	20 LF	N/A	<1 25 10	<1 <1 <1
HA-025	Glass Glaze		N/A	N/A	<1	<1
HA-026	Drywall	Paper Gypsum	N/A	N/A	<1 <1	<1 <1
HA-027	Drywall	Paper Gypsum	N/A	N/A	<1 <1	<1 <1
HA-028	Drywall		N/A	N/A	<1	<1

Notes:

bold/highlighted= Sample result detected above reporting limit

N/A Not Applicable LF Linear feet ft^2 Square feet


Friable asbestos material is defined by 40 CFR §61.141 as any material containing more than 1% asbestos by weight that when dry can be crumbled or reduced to powder by hand pressure.

Samples were analyzed in accordance with test methods EPA 600/R-93/116 Method.

Samples were collected on May 17, 2016 and submitted to Michigan OSHA/Occupational Health Laboratory for analysis under TDD No. S05-0001-16-05-001.

APPENDIX B FIGURES





2,000

4,000

0



Legend
Site Boundary

0 150 300 Feet


Disclaimer: This map is intended for visual orientation use only. In no way is this map to be used for precise locational use.



DYMET SITE MUSKEGON, MUSKEGON COUNTY, MI TDD No. S05-0001-16-05-001

> FIGURE 2 SITE FEATURES MAP





APPENDIX C ASBESTOS SAMPLE SUMMARY REPORT



ASBESTOS HOMOGENEOUS AREA SUMMARY REPORT

Homogeneous Area Number	Homogeneous Area Description	Asbestos Content	Quantity LF=Linear Feet SF=Square Feet	Friable Material (Y/N)
нА. 4 001	South Entrance	AIR CELL	30 LF	Y
HA-002 _	South Entrance	AIR CERL	30LF	<i>Y</i>
HA-003	South Entreunce	AIR CELL	30LF	4
HA-004	Basement Boiler	MAG-Plping	305	X
HA-005	Basement Boiler	MAG-piping	300F	*
HA-006	Basement Boiler	MAG-piping	300	X
HA-007	boiler	MAG facing	480 AP2	X
HA-008	Boiler	MAG-facing	480412	
HA-009	Boller	MAG-facing	480/12	
HA-010	Floor tile & mastic-	lobby & office	7250.At	N
HA-011	Floor tite & mastic	lobby & office	2250f2	N
HA-012	Floor tile & Massic	lobay & office	2250/12	N
НА-013	Insulation	office	•	N
H Λ -014	Institution = Wall Leading	office	1200 H2	N
HA-015	Institution Wall Coaling	office	1200 Ag2	N
HA-016	Wall Coating	office	12000/12	N

HA-017	Vesibule Ceiling	Latte	1000AZ N
HA-018	Vestibule Ceiling	Lathe	wyp N
HA-019	Vestibule Ceiling	Lathe	1000ff2 N
HA-20	Furnace Room	Furnace FIRE Brlik (suspect Media)	+3280/12

ASBESTOS HOMOGENEOUS AREA SUMMARY REPORT

Homogeneous Arca Number	Homogeneous Area Description	Asbestos Content	Quantity LF=Linear Feet SF=Square Feet	Friable Material (Y/N)
на-баба	Furnace Room	external insulation		
нл-992_	Furnae Rom	til Hill	1	
HA-0 2 33	PIPE MM-print shop pipe Min-ellow	roof drawn	201F	
нл-024	pipe run-elbow	roof drain	ZOLF	
на-005	piet ften glass	all windows	·	
на-Ж	dry wall	Hyroughout offices		
на-89	dry wall	throughout offices	•	
на-28	drywall	throughout offices		
HA-009				
HA-010				
HA-011				
HA-012				
HA-013				
HA-014				
HA-015				
НА-016				

-									Остра		11041	LII LAGE	orat	Ory						
1. R	eporting I				2. Inspe	3. Sampling Number														
4. E	stablishme		e								5. P	ublic/P	rivate	(For C	onsulta	tion 11	se only	<u></u>		
DYI	MET		1' (0									Self-H	elp	<u> </u>	Public		Priv	vate		
0. P	erson Perfor		6 I	ignature)	u 6	Tahu	Pome		7. CSH	O ID	8. Sampling Date 9. Shipping Date 5-17-16						g Date			
10.	Employee			۲	A.	·	Long	OY J	h Title	150			_	φ	<u></u>					
<u> </u>				<u>csa·</u>	1-11	<u>.50</u>		(1. 3(20	<u> </u>	A-12								
1.4. 1	Exposure In	Iormatior	n a. N	umber:	b. 1	reque					13. Photo(s) Yes No									
14.	15,	16.	17.	18.	19.	20.	Exposure S	3umn 22.	123.	24 C	Citation/Hazard Information									
	Substance	Rqstd.	Smpl.	Exp.	Exposure		PEL	Adj.	Severity		FTA				Trng.	Med.	Other	No		
No. 1.	Code		Туре	Туре	Level		 	-		Cit.		Exp.						Haz.		
-					-		-		<u> </u>					····		· <u>-</u>		L		
2.									ļ	-	_									
3.	1								ļ											
4.																				
5.																				
25. A	dditives (Ent	er Line Nu	umbers for	those agent	s contributin	g to add	litive effect)													
26.	Total Num	ber of L	ines (14)):	27	pratory:														
28 .]	Pump Mod	el:	•		Pump #: Sampling							ig Data								
29. 8	Sample Sul	bmissior	Numbe	ľ	HA-0	01	HA-OC	22	HA-C	03	HA		7	L114 I	かだ	Н	A-00			
30. 5	Sample Ty	pe/Medi	a		Air C	`	Air Ce		Aug al	200	-/ / / / 	r De	<u> </u>	MA 0	Ω·.	Man	NO 1	<i>21</i> 0		
31. I	Filter/Tube	Numbe	r		HAY C	<u>ver</u>	MILL		Air	cery	JY II	d Lib	8 /	MG.	riping		No 17	Ang		
32.	Γime On			<u> </u>		-							-					\preceq		
·	Γime Off				-								-							
33. T	Total Time	(in min	utes)										_							
34. I	Flow Rate	☐ 1/n	nin [] ml/min									-							
35. V	Volume (in	liters)						-								<u> </u>				
36. I	ab Sample	Numbe	 er	 ·	1622	ফ	16224	\wedge	666	T	166	2246)	42	112	16	വ	11		
37.	Analyze	For:		38. RL*	1CCC		ICCXX.	<u> </u>	TOOX	Res	ults		<u>~ 11</u>		<u>~₹</u>)	ЦС	<u> </u>			
1.	9020	5/26	116	1%	30 chays	,tile	30 chage	tile	30 chuys	المالمون	20 cl	unsoli	9 3	Oche	sotile	20	chayso	file.		
2.											_	د تاحادا:			Julite	1 -	rocido			
3.		·																		
1.												****					"			
5.																				
	Results exp		, -		less otherv		oted. 40.	Test	Method:	040	. Zoo	414	020	، ن بىر د	シ レノコ	21		-		
41. 1	nterferences	and IH (Comment:	s to Lab	42. Suppo		Samples		4			Custody	y	Ι	ate		Initial	S		
					a. Blank	s:			-		eals Ir			Y	N	4 <u> </u> e	B			
												n Lab		5/19/16			PA			
44.	Analvst's (lommen	ts		1 To 11							y Anal		5/25/16			hugy			
F	44. Analyst's Comments F2016 6290					4.74						Anal. Completed 5/24/16					breffe?			
					<u> </u>						alc. Checked 5-27-16 Aw/91									
* Rei	orting Lin	nit			Samples N	upr. OK'd 5-27-16 4/4/4/1														

1. R	eporting I	0			2. Inspec	3. Sampling Number												
4. E	stablishme	مرحگا ent Name								.	5. Public/Private (For Consultation use only)							
DYN	ÆT										Self-Help Public Private							
6. Pe	erson Perfor	_	**		. (11	1)	Λ	7. CSH									
	Zere			csay	X (Not	n_T	omrey				5-17-16							
10.	Employee	Name:	lere.	<u>Sa o</u>	Duc.	Sa	y	11. J	ob Title:	2	EQA-12							
12. E	Exposure In	formation	a. Nu	mber:	b. F	reque	hcy:			13. Photo(s) Yes No								
	T"	,	T.	T	T -		Exposure S	-,	_,	24. Citation/Hazard Information								
14. Line	15. Substance	16. Rastd	17. Smpl.	18. Exp.	19. Exposure	20.	21. PEL	22. Adj.	23. Severity	L	itation/ FTA	,			Trng	Med	Other	No
No.	Code	reque	Туре	Туре	Level	Omis	1111	ruj.	50,011	Cit.		Exp.	Liig.	1112	IIIIg.	Iviou,	Other	Haz.
1.																		
2.																		
3.																		
4.								\vdash			 							
5.								\vdash		-								
	L dditives (Ent	ter Line Ni	imbers for t	hose agents	 contributin	g to add	litive effect)	ļ	-									
L	<u> </u>								10	<u> </u>								
—	Total Num		ines (14):		, '	. Dat	m Laboratory: Sampling Data											
	Pump Moc		NT 1		Pump #:						Ī					1/0 01-		
<u> </u>	Sample Su				HA-OC	•	HA-008		•		mare 1			<u> HA-</u>		H		12
30. 8	Sample Ty	pe/Medi	a 		MAG F	car in Car	MAG Focing		MAG !	<u>adno</u>	1-100 4 M	rtile	۲ د د	-loor	Jily She	Flo	957	ile
31.]	Filter/Tube	Numbe	r			0		Û		U		, ,						
32. ′	Γime On																	
	Γime Off																	
33. 7	Γotal Time	(in min	utes)															
34. 1	Flow Rate	☐ 1/n	nin 🗌] ml/min													•	
35. Y	Volume (ir	ı liters)																
36. I	Lab Sampl	e Numbe	er		1622	万	16221	46	162	62047 162048 162049 166							<i>,</i> 22≥	'n
37.	Analyze	For:		38. RL*						Res	ults					-,,		
1.	9020	S/2	<i>c</i> //6	10/0	NDL1-C	ands	20 chysth	<u> "grey</u>	ND4-C	andes	3chey	<u>s.t.lt:</u>	6	10r -	glue	301	ysatile.	- 1. le
2.					NDL1-W	120	ND4 -u	rs A	25chysol	le-mud	HDL	l-mesti	ic 3	chefsot	ile-4:16	ND	-) - precs	,tic
3.			=		20chegentil	- gray	NDCI-W	iite	•				N)JL -1	nestic			
4.					20chysti		\$											
5.					Derveillit													
	Results exp				ess other			Tes	t Method					4 6-600		<u>5. l</u>		
41.	Interference	s and IH	Comments	to Lab	42. Supp		Samples					Custod	У		Date	4	Initia	ls
					a. Blanl	KS:						ntact?		Y			ĞΦ	
												in Lab	1	[5]	— \{\` !&	2 <u>7</u>	#1	1.0
44	Analweth	Commer	1ts		b. Bulks:						c. Rec'd by Anal. 5 25 116 lunger							
	44. Analyst's Comments F2016 0290					D. Duiks:						e. Calc. Checked 5/26/16 huggy						
	- -	•									1 1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1							
* Re	porting Li	mit			Samples_	NOT b	lank correc	ted un	f. Supr. OK'd 5-27-16 MM/1 Samples NOT blank corrected unless otherwise indicated. Results relate only to the items tested									

1. R	eporting I	D ,			2. Inspe	3. Sampling Number												
4 E	stablishme	net				E Dublic Dubrata (D. C.)												
DYI	ÆT.										5. Public/Private (For Consultation use only) ☐ Self-Help							
	erson Perfor		opling (Si	gnature)	6		<u>"U</u>	1	7. CSH	ош	8. Sampling Date 9. Shipping Date							
1	Teres	an	بسر	coo	y W	ohr	1 Tomp	oy			5-17-16							
10.	Employee	Name:	Ter	165	& De		Say 1	[1. J	ob Title:	٤	$\mathcal{L}Q$	A-	12					
12. I	Exposure In	formation	a. Ni	umber:	b. F	reque	ncy:					13.	Phot	o(s)		es		No
			·, · · · · · · · · · · · · · · · · · ·		1		Exposure S	Sumn	nary									
14. Line	15. Substance	16. Rastd	17. Smpl.	18. Exp.	19. Exposure	20.	21. PEL	22. Adj.	23. Severity	24. C No	itation/l	Hazard I Over			Tr 1	N (- 1	O41	CXI.
No.	Code	requie.	Туре	Туре	Level	Onits	100	Auj.	Severity	Cit.	1 171	Exp.	ing.	PPE	Trng.	ivica.	Other	No Haz,
1.																		
2.																		
3.																		
4.											-							
5.								_										<u> </u>
	L Additives (Ent	er Line Nu	imbers for	those agents	 contributin	g to add	litive effect)											
	Total Num					27. Date Results Received from Laboratory:												
	Pump Mod		1103 (14)	•	Pump #:	g Data												
 	Sample Su		Number	.	HA-013 HA-014 HA-015								,		~ /7	11.	1 2	
	Sample Ty				HII O	1.0	HH-01	4	17/4-6	/ <u>//</u>	77/7	- <i>0/(</i>	2 1		017	177F	1-0 ath	18
	Filter/Tube				Insulation Well Coting Coating						Č	oati	ng	_a`	the	<u> </u>	ath	<u> </u>
										-			4			_		
	Γime On												\perp			_		
	Time Off															ļ <u></u>		
	Total Time																	
34.	Flow Rate	l/n	nin _] ml/min														
35.	Volume (in	liters)																
	Lab Sampl		r		(622)	Ĭζ	16225	2	16226	J J	160254 160255 160256							
37.	Analyze	For: الجامعية	1,	38. RL*	. 050 . 1					Res	ults					1		
1.	9020	dung4 5/2	6/16	1%	NDL		NDL		4D21-0		-				white	T		
2. 3.									Midel - t	an.	har	1-ta	<u>~ </u>	JDL 1 -	-ten	HDY	1-t	in
٥. 4.																ļ		
5.					•								<u> </u>					
	Results exp	ressed in	1 %	uni	ecc other	vice n	oted 40	Tont	Mathadi				Ц.		- 1 cm			
	nterference:		Comments		lless otherwise noted. 40. Test Method: 641- 42. Supporting Samples 43. Cha							ا ہمرار Custody	020 v		PLV 3 Date	-	Initial	s
					a. Blank						eals Ir			Y	N)	Ω	_
					 50							n Lab		5/10	2/16	A	A^{+}	
											Rec'd by Anal. 5/26/16 Augus							
	Analyst's		ts								Anal. Completed 5/24/16 Luger							
٣	F20160291					1						alc. Checked 5-27-16 AMII						
* D ~	porting Li	nit			Comula: 3	JOT 61	landa a	_ 3			ipr. O			5-2	7-16	$\perp \ell$	HIM	1/_
- VG	poruug Lli	1116			i painbles I	ום די <u>טי</u>	ank correcte	ca uni	ess otherw	vise in	uicated	. Kesu	ıts rel	ate onl	v to the	items	tested	

1. R	eporting I				2. Inspection/Visit/Intervention Number							3. Sampling Number								
4 F	stablishme	nt Name			J		5. Public/Private (For Consultation use only)													
DYN	ÆT								_		☐ Self-Help 🔀 Public ☐ Private									
6. Pe	rson Perfor	ming San	wling (Sig		/ /															
8	engs	ar	سيد	<u>Na</u>	y Co	<u>onr</u>	lomro	Y)			5-17-16									
10.	Employee	Name:	Ter	PS0	Di	ധട	od 1	1. Jo	ob Title:	\leq	2/1	/	2	_						
12. I	Exposure In	formation	1 7		b. F	requer							Photo	o(s)	Y	es		No		
					I	Exposure Summary														
14.	15.	16.	17.	18.	19.	20.	21.	22.	23.	24. Cit					[m		lout 1			
Line No.	Substance Code	Rqstd.	Smpl. Type	Exp. Type	Exposure Level	Units	PEL	Adj.	Severity	No Cit.	FTA	Over Exp.	Eng.	PPE	Trng,	Med.	Other	No Haz.		
1.			I J pc	2)10	250,01							2,1,0.								
2.																		-1		
									1.											
3.																				
4.																				
5.																				
25. A	dditives (En	ter Line Nu	mbers for t	hose agents	contributin	g to add	itive effect)							-						
26.	Total Num	ber of Li	ines (14):		27	7. Date	e Results R	lecei	ved from	Labor	atory:		1			1				
28.	Pump Mod	iel:			Pump #:				Sar	npling	ng Data									
29.	Sample Su	bmission	Number	•	HA -0	19	HA-0:	26	HA-D	HA	-02	7 1	4A-1	23	111	<u> </u>	24			
30.	Sample Ty	ne/Medi:			1 10	• •	Furna	CZ.	HA-D Exter	ral	Exte	<u>፡ </u>	ĺ.	ip.	0	100	pe R	uN		
	Filter/Tube				Lath	e	ericl		Thsu	letrèss	_T	sil	ciħċ√	Tipe	Kun		Lbo	<i>~</i>		
			r 			•														
32.	Time On																			
	Time Off																			
33.	Total Time	e (in mini	utes)										İ							
34.	Flow Rate		nin [] ml/min																
35.	Volume (ii	n liters)					•			-										
ļ	Lab Sampl				1662	1622	162260			168361			16226							
37.	Analyze	For:		38. RL*	1000		INOCK		ICCUA	Res	ults	LXK.A	<i>)</i>	<u>u</u>	mad Hadding					
1.	9020	Aug 49	Ь	1%	120×1-1	ulute	NDL		NDL	.	ND	41	1	JDC	-tan	ענא	11-can	NEG		
2.					ND61-	تنس							ζ.	Ochor	tile-wh	1 25	داريي	le 7972		
3.																	rysot.	. 7		
4.																	1			
5.						-			,				1							
	Results ex	pressed i	n %	un	less other	wise n	oted. 40.	Tes	Method	: OH	LZOC	411	9021		o PLN	3.1				
	Interference		Comment	s to Lab	42. Supp	orting				43. Ch					Date		Initia	ls		
					a. Blan	ks:				a. S	eals I	ntact?		Y			AA			
					b. F						o. Rec'd in Lab 5/9/6 PA									
						с. 3						c. Rec'd by Anal. 5/26/16 lungar								
I	44. Analyst's Comments					b. Bulks: d.					d. Anal. Completed S 24 16 Augy									
F	F2016 0291					 						Calc. Checked 5-27-16 YMM								
					Samples NOT blank corrected unless otherwise inc						Supr. OK'd 5271 MM									
* Re	eporting L	ımit			[Samples]	<u>NOT b</u>	lank correct	ed un	tess other	wise in	aicate	ı. Res	uits re	tate on	ily to th	ie item	is teste	a.		

1. R	eporting II))	<u> </u>		2. Inspection/Visit/Intervention Number							3. Sampling Number							
	stablishme	nt Name	;		ı						5. Public/Private (For Consultation use only)								
DYN		<u>سن</u> د دند.	⊃ : (C:					+	le corr	0 ID		Self-H			Public		Priv	/ate	
6. Pe	erson Perfor		7	gnature) Amou	John Pomroy) 7. CSHOID							8. Sampling Date 9. Shipping Date							
10	Kres		THE STATE OF THE S		<u>~</u>		- 1		1 524	ــــ		•		0	<u> </u>			-	
10.	Employee	Name:	ler	eser	M)MC	یادم	4 ¹	1. J	b Title:	ح	Q	A -	12	•					
12. F	Exposure In	formation	a. Ni	umber:	b. Frequency:							13. Photo(s) Yes No							
	I	I = " = "	T	T	Exposure Summary							Citation/Hazard Information							
14. Line	15. Substance	16. Rostd	17. Smpl.	18. Exp.	19. Exposure	20. Units	21. PEL	22. Adj.	23. Severity	fation/				Trno	Med	Other	No		
No.	Code	1145141	Туре	Туре	Level	Omo	122	, Aug.	Severity	No Cit,		Exp.	D,,,g,	****	11116.	iviou.	, ,	Haz.	
1.																			
2.																			
3.																			
4.																			
5.					-		<u>-</u>												
	L .dditives (Ent	er Line Nu	mbers for	those agents	contributin	g to add	itive effect)	<u> </u>											
26. Total Number of Lines (14): 27. Date Results Received from Laboratory:																			
28. I	Pump Mod	el:			Pump #: Sampling						ng Data								
29. 8	Sample Sul	bmission	Number	r	MA-025 HA-026 +			HA-C	1A-027 HA-028										
30. 5	Sample Ty	pe/Media	a		Block	loze.	Drywall ?		Drewall		Da	uval	0						
31. I	Filter/Tube	Number	ſ		y s	3 tri 7.6.2	-D1900		42141	·UX¥	9/17	/ No ccs	at-						
32.	Гime On											-							
7	Γime Off		11 1130111111																
33. T	Гotal Time	(in min	utes)																
34. I	Flow Rate	☐ 1/n	nin [] ml/min															
35. Y	Volume (in	liters)					-											·	
36. 1	Lab Sampl	e Numbe	r		1622	3	16006	#	16000	(F)	166	1266)						
37.	Analyze	For:	२५1	38. RL*						Res	ults								
1.	9020	<u></u>	اله	10/0	NDL		NDL - pi	ipu	HOL -	paper	ググ	14							
2.							4021-gy	185011	HDL - 9	ypsum			\perp						
3.	-						5 /	<u>'</u>	J/										
4.							_						\perp						
5.																			
	Results exp		1 0	unl	ess other		oted. 40.	Test	Method	: 044	-zw	4 2191	020		PLU:	3.1			
41. 1	nterference	s and IH (Comment	s to Lab	42. Supp		Samples			43. Ch			у	I	Date	_	Initial	ls	
					<u> </u>							ntact?		Y N			H-		
									-			in Lab		51916			, Chi		
44	44 Annihintin Community										c. Rec'd by Anal.				5/24/16			"1	
	44. Analyst's Comments F2016 0197										d. Anal. Completed e. Calc. Checked							}_	
l '	1 2010 0 3 1 2										3 4 7 1 1 10 10 11								
* Re	porting Li	mit			Samples	Supr. OK'd 5-27-16 gg/4/1 adicated. Results relate only to the items tested.													

APPENDIX D PHOTOGRAPHIC LOG





OSC: Jeff Kimble

Date: 05/17/16 **Photographer:** Stacey

DeLaReintrie

Photograph No.: 1 Possible ACM on piping



Site: Dymet Site Location: Muskegon, Muskegon County, MI **Contract: EP-S5-16-01** TDD: S05-0001-16-05-001

OSC: Jeff Kimble

Date: 05/17/16

Photographer: Stacey

DeLaReintrie

Photograph No.: 2 Possible ACM on piping





OSC: Jeff Kimble

Date: 05/17/16

Photographer: Stacey

DeLaReintrie

Photograph No.: 3Possible ACM on boiler

exterior



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001

OSC: Jeff Kimble

Date: 05/17/16 **Photographer:** Stacey

DeLaReintrie

Photograph No.: 4Possible ACM on brick





OSC: Jeff Kimble

Date: 05/17/16

Photographer: Stacey

DeLaReintrie

Photograph No.: 5 Former boiler



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001

OSC: Jeff Kimble

Date: 05/17/16 **Photographer:** Stacey

DeLaReintrie

Photograph No.: 6

Brick piles





OSC: Jeff Kimble

Date: 05/17/16

Photographer: Stacey

DeLaReintrie

Photograph No.: 7 START and EPA collect sample DYM-DR-02.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001

OSC: Jeff Kimble

Date: 05/17/16 **Photographer:** Stacey

DeLaReintrie

Photograph No.: 8

Floor pit





Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 9Sample DYM-FLP-01 collected from floor pit.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001

OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 10 Sample DYM-FLP-01 collected from floor pit location.





OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 11 Sample DYM-FLP-02 collected from floor pit.



Site: Dymet Site Location: Muskegon, Muskegon County, MI Contract: EP-S5-16-01 TDD: S05-0001-16-05-001


OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 12 Sample DYM-FLP-02 collected from floor pit location.





Date: 05/17/16

OSC: Jeff Kimble

Photographer: Katherine

Cooper

Photograph No.: 13 Sample DYM-SOL-03 collected from container solids.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001

OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 14
Solids container from which sample DYM-SOL-03 was collected.





Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 15 Sample DYM-SOL-05 collected from floor solids.



Site: Dymet Site **Location:** Muskegon,

Muskegon County, MI **Contract:** EP-S5-16-01 **TDD:** S05-0001-16-05-001 **OSC:** Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 16 Sample location from which floor solids sample DYM-SOL-05 was collected.





OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 17 Sample DYM-SOL-07 collected from floor solids.



Site: Dymet Site **Location:** Muskegon,

Muskegon County, MI **Contract:** EP-S5-16-01 **TDD:** S05-0001-16-05-001 **OSC:** Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 18
Sample location from which floor solids sample DYM-SOL-07 was collected.





Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 19
Labeled container on top of floor solids from which sample DYM-SOL-07 was collected.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001
OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 20 Sample DYM-SC-01 and duplicate sample DYM-SC-02 collected from small container labeled Aquatic Research - Muriatic Acid.





OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 21
Sample DYM-SC-03
collected from small
container labeled Telstar –
DTR 600 – Acrylic Enamel
Reducer.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001

OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 22
Sample DYM-DR-01
collected from drum labeled
Cyanobrik - Sodium
Cyanide located in the west
building.





Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 23 Drum labeled Sodium Cyanide, 98.0% min., Poison from which sample DYM-DR-01 was collected.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001
OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 24
Sample DYM-DR-02
collected from drum labeled
Oxidizer.






Date: 05/17/16

OSC: Jeff Kimble

Photographer: Katherine

Cooper

Photograph No.: 25
Drum labeled Corrosive and
Oxidizer from which
sample DYM-DR-02 was
collected.



Site: Dymet Site **Location:** Muskegon,

Muskegon County, MI **Contract:** EP-S5-16-01 **TDD:** S05-0001-16-05-001 **OSC:** Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 26 Oxidizer drum labeled Nitric Acid from which sample DYM-DR-02 was collected.





Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 27
Oxidizer drum staging at

Oxidizer drum staging area in west building from which sample DYM-DR-02 was

collected.



Site: Dymet Site **Location:** Muskegon,

Muskegon County, MI **Contract:** EP-S5-16-01 **TDD:** S05-0001-16-05-001 **OSC:** Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 28

Example of one of the many small containers located at the Site, labeled Formaldehyde 37%.





Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 29 Location of small container labeled Formaldehyde 37% at Site.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001
OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 30
East building where floor pits, floor and container solid sample locations were located.






Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 31 Typical drum staging area at the Site. This area has approximately 9 drums.



Site: Dymet Site **Location:** Muskegon,

Muskegon County, MI **Contract:** EP-S5-16-01 **TDD:** S05-0001-16-05-001 **OSC:** Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 32
Example of one of the many drums located at the Site, labeled Texaco Merope 150.





OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 33
Example of one of the many drums located at the Site, labeled Mobilarma 245.



Site: Dymet Site **Location:** Muskegon,

Muskegon County, MI **Contract:** EP-S5-16-01 **TDD:** S05-0001-16-05-001 **OSC:** Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 34
Typical drum staging area in the west building at the Site. This area has approximately 9 drums.





Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 35
Typical drum staging area at the Site. This area has approximately 6 drums.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001
OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 36

Typical small container and drum staging area in the west building at the Site.
This area has approximately 3 small containers and 3

drums.





Date: 05/17/16

OSC: Jeff Kimble

Photographer: Katherine

Cooper

Powders.

Photograph No.: 37
Example of one of the many small containers located at the Site, labeled Metallic



Site: Dymet Site **Location:** Muskegon,

Muskegon County, MI **Contract:** EP-S5-16-01 **TDD:** S05-0001-16-05-001 **OSC:** Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 38

Example of one of the many small containers located in the basement at the Site, labeled Paper and Frisked

Cement.






Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 39

Example of one of the many unlabeled small containers located in the basement at the Site.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001

OSC: Jeff Kimble

Date: 05/17/16


Photographer: Katherine

Cooper

Photograph No.: 40

Location of small container labeled Paper and Frisked Cement and unlabeled small container in basement at

Site.






Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 41

Large pool of water near the south entrance of the west building. The floor in front of the window is also wet.



Site: Dymet Site
Location: Muskegon,
Muskegon County, MI
Contract: EP-S5-16-01
TDD: S05-0001-16-05-001
OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 42

Large opening in the roof of

the east building.





OSC: Jeff Kimble

Date: 05/17/16

Photographer: Katherine

Cooper

Photograph No.: 43
55-gallon drum labeled
"Regular Mineral Spirits"
located in the southeast
corner of the east building.



APPENDIX E VALIDATED ANAYLYTICAL DATA PACKAGE



Dymet Site – RS Final TDD No: S05-0001-16-05-001



Sustainment and Restoration Services, llc

79 W. Monroe St, Suite 1119

 Chicago, IL 60603

 (312) 220-7171

MEMORANDUM

Date: May 31, 2016

To: Tricia Edwards, OSC, US EPA Region 5

Raghu Nagam, Project Manager, SRS

Superfund Technical Assessment and Response Team (START) for Region 5

Prepared by: Richard Baldino, START QAO for Region 5

QA/QC

Concurrence by:

Subject: Data Validation for

Dymet Site

Muskegon, Michigan

Project TDD No. S05-0001-16-05-001

Laboratory: STAT Analysis, Chicago, IL Sample Delivery Group (SDG): 16050730

1.0 INTRODUCTION

The START QAO for Region 5 validated analytical data for 6 liquid and 5 solid samples for analysis of Total Metals plus Copper, Nickel, and Zinc, TCLP Metals plus Copper, Nickel, and Zinc, PCBs, Amenable Cyanide, Reactivity, Corrosivity, and Flashpoint. Samples were collected at the Dymet Site located in Muskegon, Michigan on May 17 and May 18, 2016. The samples were analyzed under SDG 16050730 by STAT Analysis Corporation of Chicago, IL using U.S. Environmental Protection Agency (U.S. EPA) methods 6020, 7470A, 7471A, 1311, 9012A, 7.3, 7.3, 8082, 1010, and E150.1.

Laboratory data were validated using guidelines set forth in the U.S. EPA Contract Laboratory Program National Functional Guidelines (NFG) for Organic Data Review (EPA-540-R-014-002, August 2014), NFG for Inorganic Data Review (EPA-540-R-013-001, August 2014), and applicable methodologies. The purpose of the chemical data quality evaluation process is to assess the usability of data for the project decision-making process.

Organic data validation consisted of a review of the following QC audits:

- Chain of custody and sample receipt forms review
- Sample preservation and holding time
- Blank results
- Surrogate recoveries
- Matrix spike and Matrix Spike Duplicate (MS/MSD) recovery results
- Laboratory Control Sample (LCS)/Laboratory Control Sample Duplicate (LCSD) recovery results

Inorganic data validation consisted of a review of the following QC audits:

- Chain of custody and sample receipt forms review
- Sample preservation and holding time
- Blank results
- Duplicate Sample Results
- LCS recovery results
- MS/MSD recovery results

Section 2.0 of this memorandum discusses the results of organic data validation. Section 3.0 of this memorandum discusses the results of inorganic data validation. Section 4.0 presents an overall assessment of

Data Validation for Dymet Project TDD No. S05-0001-16-05-001 Page 2

the data. The attachment to this memorandum contains the laboratory reporting forms as well as START's handwritten data qualifications where warranted.

2.0 ORGANIC DATA VALIDATION RESULTS

The results of START's organic data validation are summarized below by QC audit reviewed. The data qualifiers listed below were applied to sample analytical results where warranted (see attachment):

- J The analyte was detected. The reported concentration was considered estimated.
- U The analyte was not detected.
- UJ The analyte was not detected. The reporting limit was considered estimated.

After the START project staff received the data packages, they were inventoried for completeness and then reviewed according to matrix-specific protocols and data quality objectives established for the project.

2.1 LIQUID SAMPLES BY METHOD 6020, 7470A, 7471A, and 8082

2.1.1 SAMPLE HANDLING

Chain of custody documentation and sample receipt forms were reviewed to ensure requested analyses were performed and that samples arrived at the laboratory intact. Samples were collected on May 17-18, 2016 and were received on ice by the laboratory on May 18, 2016. No discrepancies were noted.

2.1.2 SAMPLE PRESERVATION AND HOLDING TIME

Samples analyzed for pH do not have a holding time, as the holding time generally an immediate field test. The holding time impacting the corrosivity of the sample is not a concern because the pH is so low.

2.1.3 BLANK RESULTS

The purpose of laboratory (or field) blank analysis is to determine the existence and magnitude of contamination resulting from laboratory (or field) activities. A laboratory method blank sample (MB-92275-PCB) was run with this SDG. No method blank detects were noted.

2.1.4 SURROGATE RECOVERIES

Laboratory performance on individual samples is established by means of fortifying each sample with surrogate compounds. Surrogate spike compounds included tetrachloro-m-xylene and decachlorobiphenyl. Surrogate recoveries were acceptable. No discrepancies were noted.

2.1.5 MS/MSD RECOVERY RESULTS

Data for MS/MSDs are generated to determine long-term precision and accuracy of the analytical method on various matrices and to demonstrate acceptable compound recovery by the laboratory at the time of sample analysis.

MS/MSD samples were not requested for this SDG. No qualification was attempted based on missing MS/MSD audit results

2.1.6 LCS/LCSD RECOVERY RESULTS

Data for the LCS/LCSD is generated to provide information on the accuracy of the analytical method and on the laboratory performance. The LCS/LCSD is fortified with Aroclor 1260 and analyzed with each batch of samples. The LCS/LCSD accuracy performance is measured by Percent Recovery (%R). LCS/LCSD recoveries were acceptable. No discrepancies were noted.

Data Validation for Dymet Project TDD No. S05-0001-16-03-001 Page 3

2.1.7 FIELD DUPLICATES

Data for field duplicates were collected and analyzed for chemical constituents to measure the cumulative uncertainty (i.e., precision) of the sample collection, splitting, handling, storage, preparation and analysis operations, as well as natural sample heterogeneity that is not eliminated through simple mixing in the field. Field duplicates are two samples prepared by mixing a volume of sample and splitting it into two separate sample containers that are labeled as individual field samples.

Field duplicate samples were not collected. No qualification was attempted based on missing field duplicate audit results.

2.1.8 GENERAL LABORATORY OBSERVATIONS

The laboratory noted that multiple samples were diluted due to high native VOC concentrations. The resulting reporting limits were elevated.

3.0 INORGANIC DATA VALIDATION RESULTS

The results of START's inorganic data validation are summarized below by QC audit reviewed. The data qualifiers listed below were applied to sample analytical results where warranted:

- J The analyte was detected. The reported concentration was considered estimated.
- U The analyte was not detected.
- UJ The analyte was not detected. The reporting limit was considered estimated.

After the START project staff received the data packages, they were inventoried for completeness and then reviewed according to matrix-specific protocols and data quality objectives established for the project.

3.1 LIQUID SAMPLES BY METHOD 9045

3.1.1 SAMPLE HANDLING

Chain of custody documentation and sample receipt forms were reviewed to ensure requested analyses were performed and that samples arrived at the laboratory intact. Solid samples were collected on April 22, 2016 and were received on ice by the laboratory on April 23, 2016. No discrepancies were noted.

3.1.2 SAMPLE PRESERVATION AND HOLDING TIME

Samples were analyzed within the holding time criteria. No discrepancies were noted.

3.1.3 BLANK RESULTS

The assessment of blank analysis results is to determine the existence and magnitude of contamination resulting from laboratory and/or field activities. Laboratory method blank samples are not required for method 9045. No discrepancies were noted.

3.1.4 LCS RECOVERY RESULTS

The LCS serves as a monitor of the overall performance of each step during the analysis, including the sample preparation. The LCS is fortified with each analyte of interest and analyzed with each batch of samples. The LCS accuracy performance is measured by %R. LCS recoveries were acceptable. No discrepancies were noted.

3.1.5 MS/MSD RECOVERY RESULTS

The spiked sample analysis is designed to provide information about the effect of each sample matrix on the sample preparation procedures and the measurement methodology. The MS/MSD accuracy performance is measured by %R.

Data Validation for Dymet Project TDD No. S05-0001-16-03-001 Page 4

MS/MSD audits are not required for method 9045. No discrepancies were noted.

3.1.6 FIELD DUPLICATES

Data for field duplicates were collected and analyzed for chemical constituents to measure the cumulative uncertainty (i.e., precision) of the sample collection, splitting, handling, storage, preparation and analysis operations, as well as natural sample heterogeneity that is not eliminated through simple mixing in the field. Field duplicates are two samples prepared by mixing a volume of sample and splitting it into two separate sample containers that are labeled as individual field samples.

Field duplicate samples were not collected. No qualification was attempted based on missing field duplicate audit results.

3.1.7 GENERAL LABORATORY OBSERVATIONS

No laboratory observations were noted.

3.2 LIQUID SAMPLES BY METHOD ASTM D92

3.2.1 SAMPLE HANDLING

Chain of custody documentation and sample receipt forms were reviewed to ensure requested analyses were performed and that samples arrived at the laboratory intact. Solid samples were collected on April 22, 2016 and were received on ice by the laboratory on April 23, 2016. No discrepancies were noted.

3.2.2 SAMPLE PRESERVATION AND HOLDING TIME

Samples were analyzed within the holding time criteria. No discrepancies were noted.

3.2.3 BLANK RESULTS

The assessment of blank analysis results is to determine the existence and magnitude of contamination resulting from laboratory and/or field activities. Laboratory method blank samples are not required for method D92. No discrepancies were noted.

3.2.4 LCS RECOVERY RESULTS

The LCS serves as a monitor of the overall performance of each step during the analysis, including the sample preparation. The LCS is fortified with each analyte of interest and analyzed with each batch of samples. The LCS accuracy performance is measured by %R.

LCS audits are not required for method D92. No discrepancies were noted.

3.2.5 MS/MSD RECOVERY RESULTS

The spiked sample analysis is designed to provide information about the effect of each sample matrix on the sample preparation procedures and the measurement methodology. The MS/MSD accuracy performance is measured by %R.

MS/MSD audits are not required for method D92. No discrepancies were noted.

3.2.6 FIELD DUPLICATES

Data for field duplicates were collected and analyzed for chemical constituents to measure the cumulative uncertainty (i.e., precision) of the sample collection, splitting, handling, storage, preparation and analysis operations, as well as natural sample heterogeneity that is not eliminated through simple mixing in the field.

Data Validation for Dymet Project TDD No. S05-0001-16-03-001 Page 5

Field duplicates are two samples prepared by mixing a volume of sample and splitting it into two separate sample containers that are labeled as individual field samples.

Field duplicate samples were not collected. No qualification was attempted based on missing field duplicate audit results.

3.2.7 GENERAL LABORATORY OBSERVATIONS

No laboratory observations were noted.

4.0 OVERALL ASSESSMENT OF DATA

The analytical results meet the data quality objectives defined by the applicable method and validation guidance documentation. The analytical data is usable and acceptable as reported by the laboratory.

ATTACHMENT SUMMARY OF VALIDATED ANALYTICAL RESULTS AND CHAIN-OF-CUSTODY

Client: Sustainment & Restoration Services, LLC

Project/Site: Dymet Site

Lab Sample ID: 500-110631-1

Matrix: Waste

TestAmerica Job ID: 500-110631-1

Date Collected: 04/22/16 11:42 Date Received: 04/22/16 15:40

Client Sample ID: BP-1

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Benzene	5.0	U	5.0	2.9	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
Carbon tetrachloride	20	U	20	7.7	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
Chlorobenzene	20	U	20	7.7	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
Chloroform	20	U	20	7.4	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
1,2-Dichloroethane	20	U	20	7.8	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
1,1-Dichloroethene	20	U	20	7.8	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
Methyl Ethyl Ketone	100	U	100	42	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
Tetrachloroethene	20	U	20	7.4	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
Trichloroethene	10	U	10	3.3	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
Vinyl chloride	10	U	10	5.2	mg/Kg		04/24/16 17:35	05/05/16 18:34	20000
Surrogate	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
1,2-Dichloroethane-d4 (Surr)	93		71 - 127				04/24/16 17:35	05/05/16 18:34	20000
Toluene-d8 (Surr)	98		75 - 120				04/24/16 17:35	05/05/16 18:34	20000
4-Bromofluorobenzene (Surr)	100		71 - 120				04/24/16 17:35	05/05/16 18:34	20000
Dibromofluoromethane	95		70 - 120				04/24/16 17:35	05/05/16 18:34	20000
General Chemistry									
Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
corrosivity by pH	1.57		0.200	0.200	SU			04/29/16 15:15	1
Flashpoint	102		40.0	40.0	Degrees F			05/04/16 00:17	1

Client: Sustainment & Restoration Services, LLC

Project/Site: Dymet Site

Client Sample ID: BP-2 Lab Sample ID: 500-110631-2

Date Collected: 04/22/16 11:50 Matrix: Waste Date Received: 04/22/16 15:40

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Benzene	2.5	U	2.5	1.5	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
Carbon tetrachloride	10	U	10	3.8	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
Chlorobenzene	10	U	10	3.9	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
Chloroform	10	U	10	3.7	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
1,2-Dichloroethane	10	U	10	3.9	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
1,1-Dichloroethene	10	U	10	3.9	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
Methyl Ethyl Ketone	50	U	50	21	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
Tetrachloroethene	10	U	10	3.7	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
Trichloroethene	5.0	U	5.0	1.6	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
Vinyl chloride	5.0	U	5.0	2.6	mg/Kg		04/24/16 17:36	05/05/16 18:08	10000
Surrogate	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
1,2-Dichloroethane-d4 (Surr)	95		71 - 127				04/24/16 17:36	05/05/16 18:08	10000
Toluene-d8 (Surr)	100		75 - 120				04/24/16 17:36	05/05/16 18:08	10000
4-Bromofluorobenzene (Surr)	100		71 - 120				04/24/16 17:36	05/05/16 18:08	10000
Dibromofluoromethane	96		70 - 120				04/24/16 17:36	05/05/16 18:08	10000
General Chemistry									
Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Flashpoint			40.0	40.0	Degrees F			05/04/16 00:33	1

Client: Sustainment & Restoration Services, LLC

Project/Site: Bethel Avenue Paint Site

TestAmerica Job ID: 500-110631-1

Client Sample ID: BP-3 Lab Sample ID: 500-110631-3

Date Collected: 04/22/16 11:56 Matrix: Waste Date Received: 04/22/16 15:40

Client: Sustainment & Restoration Services, LLC

Project/Site: Bethel Avenue Paint Site

TestAmerica Job ID: 500-110631-1

Client Sample ID: BP-4 Lab Sample ID: 500-110631-4 Date Collected: 04/22/16 11:59

Matrix: Waste

Date Received: 04/22/16 15:40

General Chemistry								
Analyte	Result Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Flashpoint	157	40.0	40.0	Degrees F			05/04/16 00:48	1

Client: Sustainment & Restoration Services, LLC

Project/Site: Bethel Avenue Paint Site

Client Sample ID: BP-5 Lab Sample ID: 500-110631-5

Date Collected: 04/22/16 12:07 Matrix: Waste Date Received: 04/22/16 15:40

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Benzene	13	Ū	13	7.3	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
Carbon tetrachloride	50	U	50	19	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
Chlorobenzene	50	U	50	19	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
Chloroform	50	U	50	19	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
1,2-Dichloroethane	50	U	50	20	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
1,1-Dichloroethene	50	U	50	20	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
Methyl Ethyl Ketone	250	U	250	110	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
Tetrachloroethene	50	U	50	19	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
Trichloroethene	25	U	25	8.2	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
Vinyl chloride	25	U	25	13	mg/Kg		04/24/16 17:38	05/05/16 19:27	50000
Surrogate	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
1,2-Dichloroethane-d4 (Surr)	98		71 - 127				04/24/16 17:38	05/05/16 19:27	50000
Toluene-d8 (Surr)	99		75 - 120				04/24/16 17:38	05/05/16 19:27	50000
4-Bromofluorobenzene (Surr)	105		71 - 120				04/24/16 17:38	05/05/16 19:27	50000
Dibromofluoromethane	95		70 - 120				04/24/16 17:38	05/05/16 19:27	50000
General Chemistry									
Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
corrosivity by pH	5.32	-	0.200	0.200	SU			04/29/16 15:32	1

Client: Sustainment & Restoration Services, LLC

Project/Site: Bethel Avenue Paint Site

TestAmerica Job ID: 500-110631-1

Lab Sample ID: 500-110631-6

Matrix: Waste

Date Collected: 04/22/16 12:18 Date Received: 04/22/16 15:40

Client Sample ID: BP-6

General Chemistry Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Flashpoint	167		40.0	40.0	Degrees F			05/04/16 01:04	1

Client: Sustainment & Restoration Services, LLC

Project/Site: Bethel Avenue Paint Site

Client Sample ID: BP-7 Lab Sample ID: 500-110631-7

Date Collected: 04/22/16 12:34 Matrix: Waste Date Received: 04/22/16 15:40

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Benzene	5.0	Ū	5.0	2.9	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
Carbon tetrachloride	20	U	20	7.7	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
Chlorobenzene	20	U	20	7.7	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
Chloroform	20	U	20	7.4	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
1,2-Dichloroethane	20	U	20	7.8	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
1,1-Dichloroethene	20	U	20	7.8	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
Methyl Ethyl Ketone	100	U	100	42	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
Tetrachloroethene	20	U	20	7.4	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
Trichloroethene	10	U	10	3.3	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
Vinyl chloride	10	U	10	5.2	mg/Kg		04/24/16 17:40	05/05/16 19:01	20000
Surrogate	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
1,2-Dichloroethane-d4 (Surr)	93		71 - 127				04/24/16 17:40	05/05/16 19:01	20000
Toluene-d8 (Surr)	102		75 - 120				04/24/16 17:40	05/05/16 19:01	20000
4-Bromofluorobenzene (Surr)	99		71 - 120				04/24/16 17:40	05/05/16 19:01	20000
Dibromofluoromethane	95		70 - 120				04/24/16 17:40	05/05/16 19:01	20000
General Chemistry									
Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
corrosivity by pH	1.61		0.200	0.200	SU			04/29/16 15:38	1

Client: Sustainment & Restoration Services, LLC

Project/Site: Bethel Avenue Paint Site

TestAmerica Job ID: 500-110631-1

Client Sample ID: BP-8 Lab Sample ID: 500-110631-8

Date Collected: 04/22/16 12:47 Matrix: Waste Date Received: 04/22/16 15:40

General Chemistry

Analyte Result Qualifier RI MDI Unit D Prepared Analyzed Dil Fac

Analyte Result Qualifier RL MDL Unit D Prepared Analyzed Dil Fac 0.200 0.200 SU 04/29/16 15:44 1

Client: Sustainment & Restoration Services, LLC

Project/Site: Bethel Avenue Paint Site

Client Sample ID: BP-9 Lab Sample ID: 500-110631-9

Date Collected: 04/22/16 12:59 Matrix: Waste Date Received: 04/22/16 15:40

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Benzene	27		13	7.3	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
Carbon tetrachloride	50	U	50	19	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
Chlorobenzene	50	U	50	19	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
Chloroform	50	U	50	19	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
1,2-Dichloroethane	50	U	50	20	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
1,1-Dichloroethene	50	U	50	20	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
Methyl Ethyl Ketone	290		250	110	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
Tetrachloroethene	50	U	50	19	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
Trichloroethene	25	U	25	8.2	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
Vinyl chloride	25	U	25	13	mg/Kg		04/24/16 17:42	05/05/16 19:54	50000
Surrogate	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
1,2-Dichloroethane-d4 (Surr)	94		71 - 127				04/24/16 17:42	05/05/16 19:54	50000
Toluene-d8 (Surr)	101		75 - 120				04/24/16 17:42	05/05/16 19:54	50000
4-Bromofluorobenzene (Surr)	103		71 - 120				04/24/16 17:42	05/05/16 19:54	50000
Dibromofluoromethane	94		70 - 120				04/24/16 17:42	05/05/16 19:54	50000

>>> Select a Laboratory <<<

Sustainment and Restoration Services LLC (SRS)

Client Contact

Sample Identification

BP-1

Phone

500-110631 COC

FAX

Chain of Custody Record

Project Manager: Rich Baldino

Sample

Time

1142

TAT if different from Below

2 weeks

1 week

2 days

1 day

Sample Type

(C=Comp,

G=Grab)

Tel/Fax: (312) 914-0325

CALENDAR DAYS

4

Sample

Date

4/22/2016

Te	est/	/m	eri	ca
TLUE I	CANCEL	CENTRE	LATINGE MAIN	TECTION

#N/A	
#N/A	
#N/A	

79 W. Monroe Street

Project Name: Bethel Avenue Paint

Site: Bethel Avenue Paint, Indianapolis, IN

Chicago/IL/606

(312) 220-7171

(xxx) xxx-xxxx

#N/A

PO#

23456789

Regulatory Program: DW NPDES RCRA Other: TestAmerica Laboratories, Inc. COC No: Site Contact: Katherine Cooper Date: 4/22/2016 COCs Lab Contact: Therese Hargraves Carrier: **Analysis Turnaround Time** Sampler: Katherine Cooper VOCs (SW-846 8260) Total TCLP WORKING DAYS For Lab Use Only: Walk-in Client: Lab Sampling: Job / SDG No.: Presevation Flashpoint Hd Matrix Cont. Sample Specific Notes: High Hazard Sample Solvent

BP-2	4/22/2016	1150	G	Solvent	2			х	Х												1	High Hazard Sample
BP-3	4/22/2016	1156	G	Solvent	1	П	x														1	High Hazard Sample
BP-4	4/22/2016	1159	G	Solvent	1			x													1	High Hazard Sample
BP-5	4/22/2016	1207	G	Solvent	2		x		х												1	High Hazard Sample
BP-6	4/22/2016	1218	G	Solvent	1			x													1	High Hazard Sample
BP-7	4/22/2016	1234	G	Solvent	2		х		х												1	High Hazard Sample
BP-8	4/22/2016	1247	G	Solvent	1		×														1	High Hazard Sample
BP-9	4/22/2016	1259	G	Paint	1		Ī		х												1	High Hazard Sample
															Ţ							
						П															П	
reservation Used: 1= ice, 2= HCl; 3= H2SO4; 4=HNO3; 5=N	laOH; 6	ra ³ mark aran sara.	and the same of th					L				1.										
re any samples from a listed EPA Hazardous Waste? Please Listed EPA Hazardous Waste?			es for the sa	•	e	_			•		(A fe						ampl			etain		longer than 1 month)
Non-Hazard Flammable Skin Irritant pecial Instructions/QC Requirements & Comments:	Poison	В	Unkno	nwo				Ret	urn to (Client			<u>LDi</u>	sposal	by La	b			Arch	ive to	r	Months
podat instructions/QC (Vequirements & Comments.																						
Custody Seals Intact:	Custody Se	al No.:						_			emp.		: Obs	s'd:			Corr'	d:			_	herm JD No.;
Custody Seals Intact: Ves No elinquished by: Katherine Croper,	Company:	SRS		Date/Time 4/22//	6 15	40 F	Recei	iyed	Yey:	Jin.	10–7				С	omp	any	A				Date/Time:/16 1540
elinquished by:	Company:			Date/Time	:	7	Řecei	ived	by:		1				С	ompa	any:	\int_{\cdot}	,			Date/Time:
elinquished by:	Company:			Date/Time	,	F	Recei	ived	l in La	bora	toi	y:			С	ompa	any:	7	1			Date/Time: V
, , , , , , , , , , , , , , , , , , ,	<u> </u>					_		_														C MI 002 Day 4.0 dated 2/2/2016

Form No. CA-C-WI-002, Rev. 4.9, dated 2/2/2016

Login Sample Receipt Checklist

Client: Sustainment & Restoration Services, LLC

Job Number: 500-110631-1

Login Number: 110631 List Source: TestAmerica Chicago

List Number: 1

Creator: Scott, Sherri L

Question	Answer	Comment
Radioactivity wasn't checked or is = background as measured by a survey meter.</td <td>True</td> <td></td>	True	
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
The cooler or samples do not appear to have been compromised or tampered with.	True	
Samples were received on ice.	True	
Cooler Temperature is acceptable.	True	Received same day of collection; chilling process has begun.
Cooler Temperature is recorded.	True	9.3
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
Is the Field Sampler's name present on COC?	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
Appropriate sample containers are used.	True	
Sample bottles are completely filled.	True	
Sample Preservation Verified.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Multiphasic samples are not present.	True	
Samples do not require splitting or compositing.	True	
Residual Chlorine Checked.	N/A	